

TIMKEN®

THE TIMKEN COMPANY

GENERAL OFFICES

CANTON, OHIO, U.S.A. 44706-2798

TELEPHONE: (216) 438-3000

US EPA RECORDS CENTER REGION 5



494520

April 12, 1989

Mr. Kelvin Rogers
Ohio Environmental Protection Agency
Northeast District Office
2110 East Aurora Road
Twinsburg, OH 44087-1969

Dear Mr. Rogers:

This letter is to inform you of two overages at our outfall #015 during March 1989. These overages were on the monitored element - total zinc - and occurred on March 17 and 27. These periodic "spikes" have occurred occasionally in the past. A task team has identified and removed some process wastes which could have been responsible for these spikes in the past. Still, we are at a loss to explain or pinpoint the cause of these spikes; however, we will continue to identify and remove any suspect processes.

If you have any questions regarding this information, please contact me.

Sincerely,

William E. Lacure
Environmental Control
Coordinator

rjm/B:368.wel

RECEIVED

APR 17 1989

OHIO EPA-N.E.D.O.